

BUVO

A COMPANY
OF
SPECIALISTS

BUVO

Achterdijk 25
5705 CB Helmond
The Netherlands

Phone +31(0)492 - 54 64 94

info@buvocastings.nl

www.buvocastings.nl

BUVO

CASTINGS

VEILIGHEID VOOROP!



Welkom bij BUVO Castings

We heten je van harte welkom bij BUVO Castings. We zijn trots op onze productiefaciliteiten en onze specialisten. Dit laten we onze bezoekers graag zien en met veel plezier en enthousiasme presenteren we jullie "ons BUVO".

Dit doen we echter niet zonder je op de hoogte te stellen van de geldende veiligheidsmaatregelen. Jouw veiligheid en de veiligheid van onze collega's staan immers voorop.

Het BUVO-team

Aan- en afmelden

Al onze bezoekers in beeld

Bij ieder bezoek dien je je aan te melden bij onze receptie. Onze receptie vind je bij de hoofdingang aan de Achterdijk 25 te Helmond. De receptioniste zal je vragen om jouw gegevens te noteren, zodat we bij eventuele noodsituaties te allen tijden op de hoogte zijn van alle bezoekers in ons pand. Na afloop van je bezoek dien je je af te melden bij de receptie.

P Parkeren Speciaal voor onze bezoekers

Je kunt parkeren op de daarvoor bestemde bezoekersparkeerplaatsen welke te vinden zijn bij onze hoofdingang. Indien deze bezet zijn, kun je je melden bij de receptioniste. Zij zal je naar een andere locatie wijzen.



Algemene regels Wat moet je weten

Roken is, m.u.v. de aangewezen rookplekken, in alle BUVO gebouwen verboden.

Drugs en alcohol zijn verboden, zowel in de gebouwen als op het terrein.

Alle bezoekers dienen enkel onder begeleiding van een BUVO medewerker de productiefaciliteiten te betreden.

Blijf gedurende de fabrieksbezoeken binnen de gele lijnen.



Binnen BUVO is het verboden te fotograferen.

Jouw BUVO begeleider geeft je graag verdere informatie en zal jouw vragen beantwoorden.



Werkverkeer Waar moet je op letten?

Binnen de productielocaties is werkverkeer aanwezig. Deze hebben altijd voorrang. Houd hier rekening mee.

In de gieterij is transport van vloeibaar aluminium aanwezig. Bezoekers dienen derhalve altijd voldoende afstand te houden van alle transportvoertuigen en op de looppaden te blijven.



Veiligheidsmiddelen Wat moet je aan?

Alle bezoekers dienen tijdens hun bezoek aan de productiefaciliteiten veiligheidsmiddelen te dragen. Dit betreft veiligheidsschoenen, veiligheidsbril en gehoorbescherming. Al deze zaken worden door BUVO beschikbaar gesteld indien de bezoeker hier niet zelf over beschikt. Deze zijn verkrijgbaar bij de BUVO receptie.



Bij ongevallen Wat moet je doen?

Verbanddozen bevinden zich op diverse locaties in de BUVO gebouwen en zijn te herkennen aan het logo met het witte kruis. Indien nodig zal jouw BUVO begeleider de BHV-verantwoordelijke(n) oproepen voor het gebruik hiervan.



In het geval van ontruiming zul je hiervoor gewaarschuwd worden door een hard en herkenbaar ontruimingssignaal. Jouw BUVO begeleider zal jou begeleiden naar de verzamellocatie aan de voorzijde van ons pand, waar je dient te wachten op verdere instructies van de BHV'ers (herkenbaar aan de heses). De dichtstbijzijnde uitgangen zijn te herkennen aan de borden. Vluchtroutes zijn aangegeven op de plattegronden op locatie.



SAFETY FIRST!

BUVO

A COMPANY
OF
SPECIALISTS

BUVO

Achterdijk 25
5705 CB Helmond
The Netherlands

Phone +31(0)492 - 54 64 94

info@buvocastings.nl

www.buvocastings.nl



Welcome to BUVO Castings

We would like to welcome you to BUVO Castings. We are proud of our production facilities and what we do and therefore we like to show these facilities to our visitors.

To do this, however, we must inform you of our safety measures that we have in place when you visit our production facilities. Your safety, and the safety of our colleagues, always comes first.

The BUVO team

Signing in and signing out

You should report to our reception on each visit. This reception is located at our main entrance on the Achterdijk 25 in Helmond. The receptionist will ask you to record your details so that in an emergency situation we know at all times who is on the premises. On your departure you should once more report to reception.

Parking Specially for our visitors

You may park in the visitor parking spaces for this purpose which are located near our main entrance. If there are no free spaces, please report to the receptionist. She will direct you to another location.

General rules What you need to know

Smoking is forbidden in all BUVO buildings, except for the smoking areas indicated.

Drugs and alcohol are forbidden, both in the buildings and on the site.

All visitors may only enter the production facilities accompanied by a BUVO employee.

Stay within the yellow line during factory visits.

It is forbidden to take photographs in BUVO.

The BUVO employee who accompanies you will be happy to provide you with further information and to answer your questions.



Work traffic What should you look out for?

Work traffic is present within the production locations. This always has priority. Pay attention to this.

Liquid aluminium is transported in the foundry. Visitors should therefore always keep sufficient distance from all transport vehicles and remain on the walkways.



Safety Equipment What should you wear?

All visitors should wear safety equipment during their visit to the production facilities. This means safety shoes, safety goggles and hearing protection. All these items are made available by BUVO if the visitor does not have them him/herself. They are available from the BUVO reception.



In the case of accidents What should you do?

You will find first-aid boxes in various locations in the building and these can be recognised by the logo. The BUVO employee who is accompanying you will call the emergency response team.



In the case of evacuation, you will be informed of this by a loud and recognisable evacuation signal. The BUVO employee accompanying you will take you to the assembly location at the front of our building where you should wait for further instructions from the inhouse emergency response team (recognisable by their vests). The closest exits are indicated on the signs. Emergency escape routes are indicated on the maps at the location.

